


Dual Encoded ABS Bearing — Installs Right the First Time!



SureSignal™ Dual Encoder

Dual magnets eliminate any chance of installing incorrectly!

National dual encoder bearings — with new SureSignal™ technology — contain magnetic encoders on *both* sides of the bearing, eliminating installation error and potentially saving technicians time and money. In addition, SureSignal technology delivers a bearing with seals that avoid the entrance of external particles and water.

Always be on the right side; choose National SureSignal bearings.

See other side for part numbers and applications.



SureSignal™ makes sure the job is done right the first time!



To view all part numbers visit drivcat.com*

PART NUMBER	APPLICATION
510056	Ford EcoSport (Whl) 2013-10; Ford EcoSport (Whl) 2019-18; Ford Fiesta (Whl) 2001; Ford Fiesta (Whl) 2019-03; Ford Fiesta Ikon (Whl) 2004-02; Ford Focus (Whl) 2011-00; Mazda 2 (Whl) 2014-11
510073	Acura CSX (Whl) 2011-06; Acura ILX (Whl) 2019; Acura TL (Whl) 2008-04; Acura TSX (Whl) 2008-04; Honda Accord (Whl) 2007-03; Honda Civic (Whl) 2011-06; Honda Civic (Whl) 2019-16; Honda Insight (Whl) 2019; Jaguar F-Type (Whl) 2018-14; Jaguar XF (Whl) 2018-09; Jaguar XFR (Whl) 2015-10; Jaguar XFR-S (Whl) 2015-13; Jaguar XJ (Whl) 2018-10; Jaguar XJR (Whl) 2017-14; Jaguar XJR575 (Whl) 2018; Jaguar XK (Whl) 2015-07; Jaguar XKR (Whl) 2015-09; Jaguar XKR-S (Whl) 2015-12; Land Rover Range Rover Evoque (Whl) 2018-12
510074	Honda CR-V (Whl) 2006-02; Honda Element (Whl) 2011-03
510082	Audi Q7 (Whl) 2016-07; Bentley Mulsanne (Whl) 2019-11; Jaguar E-Pace (Whl) 2018; Jaguar F-Pace (Whl) 2018-17; Jaguar XE (Whl) 2018-17; Jaguar XJ (Whl) 2018-13; Land Rover Discovery (Whl) 2019-17; Land Rover Discovery Sport (Whl) 2018-15; Land Rover Range Rover (Whl) 2019-03; Land Rover Range Rover Evoque (Whl) 2018-12; Land Rover Range Rover Sport (Whl) 2018-14; Land Rover Range Rover Velar (Whl) 2018; Porsche Cayenne (Whl) 2006-03; Porsche Cayenne (Whl) 2012-08; Rolls-Royce Phantom (Whl) 2019-04; Volkswagen Touareg (Whl) 2017-04
510086	Honda Odyssey (Whl) 2010-05
510087	Land Rover Freelander (Whl) 2005-02; Land Rover LR2 (Whl) 2015-08
510088	Honda Ridgeline (Whl) 2014-06; Honda Ridgeline (Whl) 2019-17
510089	Acura ILX (Whl) 2014-13; Honda Civic (Whl) 2018-06
510090	Dodge Caliber (Whl) 2012-07; Jeep Compass (Whl) 2019-07; Jeep Patriot (Whl) 2017-07; Mitsubishi Lancer (Whl) 2017-08; Mitsubishi Outlander (Whl) 2019-07; Mitsubishi Outlander Sport (Whl) 2019-11; Mitsubishi RVR (Whl) 2019-11
510091	Honda City (Whl) 2014-10; Honda Fit (Whl) 2008-06; Honda Insight (Whl) 2014-10
510092	Acura RDX (Whl) 2012-07; Honda CR-V (Whl) 2011-07; Honda HR-V (Whl) 2019-16; Honda Odyssey (Whl) 2019-18; Honda Pilot (Whl) 2019-16
510094	Scion iQ (Whl) 2015-12; Scion xD (Whl) 2014-08; Toyota Prius AWD-e (Whl) 2019; Toyota Prius C (Whl) 2019-12; Toyota Prius Prime (Whl) 2019-18; Toyota Prius V (Whl) 2018-17; Toyota Yaris (Whl) 2019-06; Toyota Yaris iA (Whl) 2018-17
510095	Acura TL (Whl) 2014-09; Acura TSX (Whl) 2014-09; Honda Accord (Whl) 2012-08; Honda Accord Crosstour (Whl) 2011-10; Honda Crosstour (Whl) 2015-12
510097	Mercedes-Benz GL320 (Whl) 2009-07; Mercedes-Benz GL350 (Whl) 2012-10; Mercedes-Benz GL450 (Whl) 2012-07; Mercedes-Benz GL550 (Whl) 2012-08; Mercedes-Benz ML450 (Whl) 2011-10; Mercedes-Benz ML63 AMG (Whl) 2011-07; Mercedes-Benz R63 AMG (Whl) 2007
510098	Honda Element (Whl) 2010-07
510101	Suzuki SX4 (Whl) 2014-07; Suzuki SX4 Crossover (Whl) 2012
510102	Mazda 6 (2.5L L4) (Whl) 2013-09
510103	Mazda 6 (3.7L V6) (Whl) 2013-09
510104	Honda CR-Z (Whl) 2016-11; Honda Fit (Whl) 2019-09

PART NUMBER	APPLICATION
510106	Ford Transit Connect (Whl) 2013-10
510108	Mercedes-Benz C300 (Whl) 2014-08; Mercedes-Benz C350 (Whl) 2015-13; Mercedes-Benz CL550 (Whl) 2014-09; Mercedes-Benz CLS400 (Whl) 2017-15; Mercedes-Benz CLS550 (Whl) 2016-12; Mercedes-Benz CLS63 AMG (Whl) 2014; Mercedes-Benz CLS63 AMG S (Whl) 2017-14; Mercedes-Benz E250 (Whl) 2016-14; Mercedes-Benz E350 (Whl) 2016-10; Mercedes-Benz E400 (Whl) 2017-13; Mercedes-Benz E550 (Whl) 2016-10; Mercedes-Benz E63 AMG (Whl) 2015-12; Mercedes-Benz GLK250 (Whl) 2015-13; Mercedes-Benz GLK350 (Whl) 2015-10; Mercedes-Benz S350 (Whl) 2013-12; Mercedes-Benz S550 (Whl) 2013-08
510110	Ford C-Max (Whl) 2018-13; Ford Escape (Whl) 2019-13; Ford Focus (Whl) 2018-12; Ford Transit Connect (Whl) 2018-14; Lincoln MKC (Whl) 2019-15
510112	Alfa Romeo Mito (Whl) 2012; Fiat 500 (Whl) 2018-12; Fiat 500X (Whl) 2018-16; Nissan March (Whl) 2014-12; Nissan Micra (Whl) 2017-15; Nissan Platina (Whl) 2010-02; Nissan Versa (Whl) 2019-10; Nissan Versa Note (Whl) 2019-14
510116	Dodge Durango (Whl) 2019-11; Jeep Grand Cherokee (Whl) 2019-11; Mercedes-Benz GL350 (Whl) 2016-13; Mercedes-Benz GL450 (Whl) 2016-13; Mercedes-Benz GL550 (Whl) 2016-13; Mercedes-Benz GL63 AMG (Whl) 2016-13; Mercedes-Benz GLE300d (Whl) 2016; Mercedes-Benz GLE350 (Whl) 2018-16; Mercedes-Benz GLE350d (Whl) 2016; Mercedes-Benz GLE400 (Whl) 2018-16; Mercedes-Benz GLE450 AMG (Whl) 2016; Mercedes-Benz GLE550 (Whl) 2016; Mercedes-Benz GLE550e (Whl) 2016; Mercedes-Benz GL63 AMG (Whl) 2016; Mercedes-Benz GLE63 AMG S (Whl) 2016; Mercedes-Benz Metris (Whl) 2018-16; Mercedes-Benz ML250 (Whl) 2015; Mercedes-Benz ML350 (Whl) 2015-12; Mercedes-Benz ML400 (Whl) 2015; Mercedes-Benz ML550 (Whl) 2015-12; Mercedes-Benz ML63 AMG (Whl) 2015-12
510117	Acura MDX (Whl) 2018-14; Acura RDX (Whl) 2018-13; Acura RLX (Whl) 2017-14; Honda Clarity (Whl) 2019-18; Honda CR-V (Whl) 2018-12
510118	Acura RLX (Whl) 2017-16; Acura TLX (Whl) 2019-15; Honda Accord (Whl) 2018-13
510119	Buick Encore (Whl) 2019-13; Chevrolet Sonic (Whl) 2019-12; Chevrolet Spark EV (Whl) 2016-14; Chevrolet Trax (Whl) 2019-13
510122	Mitsubishi Mirage (Whl) 2015-14
511029	Honda CR-V (Whl) 2006-02
511033	Honda Ridgeline (Whl) 2014-06
511041	Mercedes-Benz GL320 (Whl) 2009-07; Mercedes-Benz GL350 (Whl) 2012-10; Mercedes-Benz GL450 (Whl) 2012-07; Mercedes-Benz GL550 (Whl) 2012-08; Mercedes-Benz ML320 (Whl) 2009-07; Mercedes-Benz ML350 (Whl) 2011-06; Mercedes-Benz ML450 (Whl) 2011-10; Mercedes-Benz ML500 (Whl) 2007-06; Mercedes-Benz ML550 (Whl) 2011-08; Mercedes-Benz ML63 AMG (Whl) 2011-07; Mercedes-Benz R320 (Whl) 2009-07; Mercedes-Benz R350 (Whl) 2013-06; Mercedes-Benz R500 (Whl) 2007-06; Mercedes-Benz R63 AMG (Whl) 2007
511044	BMW 1 Series M (Whl) 2011; BMW 135i (Whl) 2013-08; BMW 135is (Whl) 2013; BMW 325xi (Whl) 2006; BMW 328i (Whl) 2013-07; BMW 328i xDrive (Whl) 2013-09; BMW 328xi (Whl) 2008-07; BMW 330i (Whl) 2006; BMW 330xi (Whl) 2006; BMW 335d (Whl) 2011-09; BMW 335i (Whl) 2013-07; BMW 335i xDrive (Whl) 2013-09; BMW 335is (Whl) 2013-11; BMW 335xi (Whl) 2008-07; BMW M3 (Whl) 2013-08
511045	Jaguar F-Type (Whl) 2018-14; Jaguar XE (Whl) 2018-17
516016	Ram ProMaster 1500 (Whl) 2018-14; Ram ProMaster 2500 (Whl) 2018-14; Ram ProMaster 3500 (Whl) 2018-14

*Running change, implemented on all new production orders. Inventory may be mixed.